42003 00032



United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025-1856

## RECEIVED

MAY 2 1 2002

May 13, 2002

Air Protection Division (3AP22)

Dr. Roger C. Westman Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Ward Kelsey, Esq.

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 02-0058

100 & 600 Carbonate Units

USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

General Manager

Clairton Works Raw Materials

## NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 02-0058
- Date & Time of Breakdown: Date: 05/13/02 Time: 1045 hours 2.
- 3. Company Name: U.S. Steel Corporation - USS Clairton Works
- 4. Specific Equipment Involved or Affected: 100 & 600 Carbonate Units
- BAPC Permit Number (if applicable): 5.
- 6. Location: Clairton, PA
- Nature and cause of breakdown: Coke Oven Gas was passed through the 7. Sulfur Plant. Debris plugged the exchangers of the 100 & 600 Carbonate Units' Process Water Coolers which inhibited their ability to adequately cool the acid gases before entering the vacuum axis.
- 8. Identification of Emissions:
  - Type(s) (CO, NOX, SO2, Particulates, Hydrocarbons, etc.) Α. Elevated H<sub>2</sub>S in the down river gas line system, causing increased SO2 at point of combustion. The 40 grain limit is not expected to be exceeded.
  - В. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO2 is an eye, nose, and throat irritant.
  - C. Amount of each type emitted (or likely to be emitted). No environmental impact is expected. The 40 grain limit is not expected to be exceeded.
- Measures taken (or to be taken) to minimize length of breakdown and 9. amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The 600 Unit Process Water Cooler was cleared of the debris and the facility was brought back on line.

Facility back in operation - Date: 05/13/02 Time: 1220 hours 10.

Signature (ilen h. Davis

Environmental Control Engineer Phone: 233-1015

\_\_\_\_ Date\_\_*5/3/02*\_\_